Security Systems

BOSCH

From		Telephone	Nuremberg	
STVC/PRM	Product Management	+49 911 93456 0	25.06.2010	

Release Letter

Product:	*Configuration Manager*
Version:	*3.21.0002*

This letter contains latest information about the above mentioned software.

1. General

Configuration Manager is a generic configuration tool for all Bosch IP Network Video Products, both software modules and hardware devices.

It is used for configuration and licensing of the various products where it is included on the product CD.

Configuration Manager version 3.21.0002 is a maintenance release based on version 3.20.0004 and is part of BVIP Lite Suite 3.21.

Make sure to always use the latest released version.

BOSCH and the symbol are registered trademarks of Robert Bosch GmbH, Germany

BOSCH

From		Telephone	Nuremberg	
STVC/PRM	Product Management	+49 911 93456 0	25.06.2010	

2. New Features

- Updated manual and help file in German and English

3. Restrictions; Known Issues

- VGA settings for VIP XD are not available in this Configuration Manager version. Must be set up via the product's web site.
- Encryption Site License (option) must be installed to make AES encryption usable.
- Under Vista when using UAC, Configuration Manager must be run as administrator for valid licensing.
- When using the Wizard to re-configure this will not work for password-protected devices.
- FTP address must be IP address only, URL is not supported.
- When the integrated iqn-Mapper shall be used in a non-VRM environment, the iSCSI configuration passwords must be set equal at all iSCSI targets.
- Alarm input rules of AutoDomes running firmware version 4.10 can not be configured correctly in Configuration Manager. The Web interface shall be used instead.
- After changing the IP address of a device the settings page might not be updated automatically. Manual refresh might be required.
- The Wizard may run into a timeout situation when configuring a camera with motion recording. A "Retry" button appears which needs to be pressed then.
- When time zone had been changed in Advanced Mode, synchronization to PC in Basic Mode does not update time zone.
- The "Save" button is not activated in Basic Mode when DHCP settings are changed.
- In Date/Time settings page, the date and time values shown are from PC instead of from device.
- Upload of a configuration file might be incomplete if it includes recording settings.
  It is recommended to check the settings manually.

Note:
If multiple Configuration Managers are used in the network, maintaining the same or an overlapping set of devices simultaneously, unpredictable effects might occur when writing to the devices.

BOSCH and the symbol are registered trademarks of Robert Bosch GmbH, Germany

From		Telephone	Nuremberg
STVC/PRM	Product Management	+49 911 93456 0	25.06.2010

4. System Requirements

Hardware	Personal Computer
CPU	Dual Core, 3.0 GHz or better
RAM	min. 2 GB
OS	Windows XP Home/XP Professional SP2/SP3, Windows Vista SP1/SP2
Graphic Card	refer to MPEG-ActiveX 4.42.03.09
Ethernet Card	100 Mbps
Sound Card	Recommended
Software	DirectX 9.0c MPEG-ActiveX 4.42.03.09 or newer
Free Memory (Installation)	145 MB (.NET environment, Viewer, Archive Player, Configuration Manager, MPEG-ActiveX)

BOSCH and the symbol are registered trademarks of Robert Bosch GmbH, Germany

Free Manuals Download Website

http://myh66.com

http://usermanuals.us

http://www.somanuals.com

http://www.4manuals.cc

http://www.manual-lib.com

http://www.404manual.com

http://www.luxmanual.com

http://aubethermostatmanual.com

Golf course search by state

http://golfingnear.com

Email search by domain

http://emailbydomain.com

Auto manuals search

http://auto.somanuals.com

TV manuals search

http://tv.somanuals.com